## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,969,221 B2

APPLICATION NO. : 10/716569

DATED

: November 29, 2005

INVENTOR(S)

: Dennis Schultz

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 1,

Line 42, after "the external" insert --surface of the threaded insert. The depth of the dovetail slot is typically greater than the depth of the male threads on the external surface of the threaded insert.--.

Signed and Sealed this

Page 1 of 1

Fifth day of September, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office